



# FACILITY COMPLIANCE INSPECTION REPORT

## Division of Waste Management

### Solid Waste Section

**UNIT TYPE:**

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY:</b> Wake <b>PERMIT NO.:</b> SLAS 92-07 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** 7/16/2014

**Date of Last Inspection:** 3/10/2014

**FACILITY NAME AND ADDRESS:**

Stallings Septic Service  
7132 Hidden Valley Trail  
Garner, NC 27529

**GPS COORDINATES:** N: 35.62024 E: -78.59184

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Bobby & Carolyn Stallings & Wallace Moore  
Telephone: (919) 779-1074  
Email address: stallingsseptic@bellsouth.net  
Fax: (919) 779-1018

**FACILITY CONTACT ADDRESS:**

Same as above

**PARTICIPANTS:**

Connie Wylie, Everett Coates  
Bobby Stallings, Wallace Moore

**STATUS OF PERMIT:**

Active-permit expires on July 29, 2015

**PURPOSE OF SITE VISIT:**

Routine

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. The cropstand looks adequate on both fields and the fields have been recently cut. Continue weed control.
2. No recent land application. No odors noted.
3. No sign of land application outside the permitted boundaries. It appears that the approved setbacks are being met.
4. Field markers need to be reposted on both fields. Ensure that the required setbacks are present on both fields, measure distances accordingly. No land application shall occur until the permitted boundaries are posted.
5. The access road is adequate and the required signs are posted.

Please contact me if you have any questions or concerns regarding this inspection report.



\_\_\_\_\_  
Connie S. Wylie  
**Regional Representative**

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	X	US Mail		Certified No. <input type="checkbox"/>
----------	--	-------	--	---------------	---	---------	--	--